

Outline
Background
Case Study 1 • Landslide Debris (Dorset)
Case Study 2 Engineering NIR Stratigraphy (Hampshire)
Case Study 3 Weathering - London Clay (London)
• University of Centre for Applied Geoscience









































































